

Appendix F – Photo Log



0718ELM01 – Facing south



0718ELM02 – Facing southwest



0718ELM03 – Facing west



0718ELM04 – Facing northwest



0718ELM05 – Facing north



0718ELM06 – Facing northeast



0718ELM07 – Facing east



0718ELM08 – Facing southeast



0718ELM09 – Standing water at southwestern edge of tank farm footprint



0718ELM10 – wood debris with potential lead paint chips
outside of tank farm footprint, on northern area of site



0718ELM11 – View from outside of site, facing southwest.



0718ELM12 – Suspected drainage pipe outside of site boundaries, at eastern corner of site



0718ELM13 – View from outside of site, facing southeast




0718ELM14 – View from outside of site, facing southeast



0718ELM15 – 2407ELIMMETBACK



0718ELM16 – 2407ELIM-CON09SS



0718ELM17 – 2407ELIM-STAIN08SS



0718ELM18 – 2407ELIM-TANK01SS



0718ELM19 – 2407ELIM-TANK02SS




0718ELM20 – 2407ELIM-TANK02SUB



0718ELM21 – 2047ELIM-TANK03SUB and 2407ELIM-TANK03SS



0718ELM22 – 2047ELIM-TANK04SS



0718ELM23 – 2407ELIM-TANK05SS (duplicate of 2407ELIM-TANK05SS), time: 2:10pm



0718ELM24 – 2407ELIM-TF10SS, time: 2:30pm



0718ELM25 – 2407ELIM-TANK06SS and 2407ELIM-TANK07SS
(duplicate of 2407ELIM-TANK06SS)



0718ELM26 – 2407ELIM-TANK13SS



0718ELM27 – 2407ELIM-DRUM11SS



0718ELM28 – Debris by drum area northeast of the tank farm



0718ELM29 – Debris by drum area northeast of the tankfarm



0718ELM30 – Facing southeast, view overlooking tank farm footprint



0718ELM31 – XRF screening samples



0718ELM32 – 2407ELIM-DRUM12, time: 3:20pm



0718ELM33 - Debris by drum area northeast of the tank farm



0718ELM34 – Area of stained soil



0718ELM35 – View of tank farm facing east



0718ELM36 – View of tank farm facing west from edge of tank farm footprint



0718ELM37 – Buried foam and soda cans found at 2407ELIM-TANK06



0718ELM38 – Suspected drainage pipe from within site boundaries, facing southeast